

报告编号	结论	报告日期	图片
DAJC-7F50002-2022	合格	2022-01-19	 A photograph showing a worker from behind, wearing a purple jacket and a red hard hat. The worker is positioned in front of a large, orange industrial machine, possibly a conveyor or a large-scale testing equipment. The machine has various pipes and components visible.
DAJC-7F50003-2022	合格	2022-01-19	 A photograph showing a worker from the side, wearing a black jacket and a red hard hat. The worker is operating a large industrial machine with a prominent circular component. The machine is situated in an industrial or laboratory setting.