


| 序号 | 报告名称 | 报告编号 | 检测检验时间 | 报告结论 | 现场勘验影像资料 |
|----|-------------|-------------------|------------|------------|---|
| 1 | 西和县中宝矿业有限公司 | DAJC/7F01042-2024 | 2024-07-02 | 综合判定该提升机合格 |  The '现场勘验影像资料' (On-site inspection image data) column contains two side-by-side photographs. The left photograph shows a person in a hard hat and safety vest standing next to a large piece of industrial machinery with warning signs. The right photograph shows a person in a hard hat and safety vest working on or inspecting a large, curved metal structure, possibly a part of a hoist or elevator mechanism. Both photos have a timestamp '2024-07-02 14:27' in the bottom left corner. |